

## ANNUAL REPORT

As of August 31, 2019

The Dane County Drainage Board submits the following annual report for the above identified drainage district for the twelve (12) month period ending August 31, 2019.

## 1. Financial statement

|   | Debts       | Credits     |
|---|-------------|-------------|
| Starting balance 9/1/18                 |             | \$ 6,730.68 |
| Assessments for costs collected         |             | \$ 525.00   |
| Interest earned on assessments          |             |             |
| Interest earned on borrowed funds       |             |             |
| Other receipts                          |             |             |
| <b>Total of all Receipts</b>            |             | \$ 525.00   |
| Amount paid out for district activities | \$ 2,509.80 |             |
| Other payables                          |             |             |
| <b>Total of all Expenditures</b>        | \$ 2,509.80 |             |
| Ending Balance on 8/31/19               |             | \$4,745.88  |
| Assessments not collected               | \$ 0.00     |             |

2. No bonds have been issued or paid during the previous twelve (12) months.

3. Amounts paid out for District activities included:

|          |                   |            |
|----------|-------------------|------------|
| 10/23/18 | Hurley Burnish SC | \$ 704.37  |
| 10/25/18 | Leonard Massie    | \$153.45   |
| 10/30/18 | Hurley Burnish SC | \$407.65   |
| 10/31/18 | Hurley Burnish SC | 4184.31    |
| 03/12/19 | Hurley Burnish SC | \$567.92   |
|          | Total             | \$2,509.80 |

Assessments collected include:

|                            |           |
|----------------------------|-----------|
| September, 2019 Collection | \$ 525.00 |
|----------------------------|-----------|

4. Work done in the district.

None

5. A review and inspection of the district found the following:

Flow in the main ditch at Cuba Valley road was good. Willows are growing rapidly along the main ditch to the north.

At the main ditch crossing Daley Road, the brush is starting to grow.

Major bank slumping and erosion where the 18-inch lateral from across CTH I enters the main drain.

Town of Vienna has installed a 3-foot diameter culvert (estimated possible flow of 14 cubic feet/second) across Norway Groove School Road to carry water from Madison Sand and Gravel Land (quarry) on the north side of the road to Madison Sand and Gravel land on the south side of the road in Section 22. The new route for flow from the north is much shorter than before to the main drain of District 29. The potential problems are the erosion of bends in the main drain of District 29 and submerging of tile outlets of on-farm drainage systems that would reduce crop yields.

6. It is the Drainage Board's practice to review the condition of the district on an annual basis and as requested by district residents. All work within the district on district facilities is approved and performed pursuant to Chapter 88 of the Wisconsin Statutes and Chapter ACTP 48 of the Wisconsin Administrative code.

I certify that the information contained in the annual report is true.

Date: September 26, 2019

Leonard R. Massie

Leonard R. Massie, Secretary of the Dane County Drainage Board

: