



ANNUAL REPORT FOR DRAINAGE DISTRICT ACTIVITIES

CHRIS CLAYTON, PROGRAM MANAGER
 AGRICULTURAL RESOURCE MANAGEMENT DIVISION
 2811 AGRICULTURE DR.
 MADISON, WI 53708—8911
 CHRISTOPHER.CLAYTON@WI.GOV
 (608) 224-4630

County Dane	District (A separate report must be submitted for each district.) 16	Date: 10/4/2017
---------------------------	--	-------------------------------

I. Financial Statement		
	DEBTS	CREDITS
Starting balance on September 1st, 2016		\$13,989.99
Assessments Collected		\$305.97
Interest earned on assessments		
Interest earned on borrowed funds		
Other Receipts		
Total of all receipts		\$305.97
Amount paid out for district activities	\$4,677.90	
Amount paid out to repay loans or bonds		
Other payables		
Total of all expenditures	\$4,677.90	
Ending balance on August 31, 2017		\$9,618.06
Uncollected Assessments		

II. The following bonds have been issued or paid during the preceding twelve months:

III. Attach sheets detailing work performed in the previous year. Include:

- A. Project description, including project cost
- B. Map showing the location of project
- C. Annual Inspection Report, major storm reports, and/or other inspection reports performed by the Drainage Board in the past twelve months

Name of Drainage Board Chairperson:	Date:
Scott Ringelsttter	10/9/17
Signature of Drainage Board Chair (please print):	
Scott Ringelstetter	

NOTE: Submit one copy of this report to DATCP, the county Zoning Administrator, the town board or town zoning committee, and the city council, plan commission, or plan committee in which district territory

ANNUAL REPORT

As of August 31, 2017

The Dane County Drainage Board submits the following annual report for the above identified drainage district for the twelve (12) month period ending August 31, 2017.

1. No work done in the district
2. A review and inspection of the district found the following:

Ditch in section 24 almost completely filled with trees. The culvert was blocked with woody debris. At Hammond Road, the CMP (corrugated metal pipe) has 2-inches of water flowing. The ditch is full of brush and needs cleaning. East of Hammond Road the culverts (6-foot dia.) were flowing. Many trees are leaning over the ditch. Buffer strip (~ 100 feet wide) has been installed along the ditch.

At CTH N, 12-inches of flow was occurring. Brush and trees are a problem. The ditch is very wide.

At Dallman Road and the railroad tracks, there was 8-10 inches of flow through the CMP. There is a pile of debris on the west side in the center of the two CMP. There is a pile of debris in the channel on the east side with flow around it.

At Washington Road, there was 3-inches of flow through the CMP's.

The district needs attention. A large area of the District is not being farmed on the north end – enrolled in the NRCS long-term wetland restoration program.

A meeting was held in 2015. The Wileman's were to get some cost estimates to provide an outlet to the district main west across Anderson land. The Board has not received any word from them.