



## ANNUAL REPORT FOR DRAINAGE DISTRICT ACTIVITIES

CHRIS CLAYTON, PROGRAM MANAGER  
 AGRICULTURAL RESOURCE MANAGEMENT DIVISION  
 2811 AGRICULTURE DR.  
 MADISON, WI 53708—8911  
 CHRISTOPHER.CLAYTON@WI.GOV  
 (608) 224-4630

<b>County</b>	<b>District</b> (A separate report must be submitted for each district.)	<b>Date:</b>
Dane	28	10/4/2017

I. Financial Statement		
	DEBTS	CREDITS
Starting balance on September 1st, 2016		\$11,319.94
Assessments Collected		\$64,800.00
Interest earned on assessments		
Interest earned on borrowed funds		
Other Receipts		
<b>Total of all receipts</b>		<b>\$64,800.00</b>
Amount paid out for district activities	\$46,506.04	
Amount paid out to repay loans or bonds		
Other payables		
<b>Total of all expenditures</b>	<b>\$46,506.04</b>	
Ending balance on August 31, 2017		\$29,933.62
Uncollected Assessments		

II. The following bonds have been issued or paid during the preceding twelve months:

III. Attach sheets detailing work performed in the previous year. Include:

- A. Project description, including project cost
- B. Map showing the location of project
- C. Annual Inspection Report, major storm reports, and/or other inspection reports performed by the Drainage Board in the past twelve months

Name of Drainage Board Chairperson: <b>Scott Ringelstetter</b>	Date: <b>10/9/17</b>
Signature of Drainage Board Chair (please print): <b>Scott Ringelstetter</b>	

**NOTE:** Submit one copy of this report to DATCP, the county Zoning Administrator, the town board or town zoning committee, and the city council, plan commission, or plan committee in which district territory

ANNUAL REPORT

As of August 31, 2017

The Dane County Drainage Board submits the following annual report for the above identified drainage district for the twelve (12) month period ending August 31, 2017.

1. Work done in the district was the cleanout of Laterals 4, 5, and 7. The cost to date was \$32,000. The spoil will be spread this fall after the crops are off. An assessment for cost in the district will be needed to reimburse the landowners that advanced the money for the cleanout.

2. A review and inspection of the district found the following:

Most ditches are lined with trees and are generally in bad shape. The lateral south of Sherman Road is in very bad condition. The dam at Merrick's has deteriorated some more. Gravel has been placed in eroded sections on the west side. A 4x4 stop log has not been removed. Flow over the stop logs was 6 – 8 inches deep.

At the Kersten – Merrick property line, water in the ditch was moving well. Flow at the south end of the corrugated metal pipe (CMP) was 6-inchs deep.

Several culverts under field roads are collapsed (bowed) and impede flow.

On Oak Park Road west of Wisconsin Highway 73, there are trees in the ditch.