



## ANNUAL REPORT FOR DRAINAGE DISTRICT ACTIVITIES

CHRIS CLAYTON, PROGRAM MANAGER  
 AGRICULTURAL RESOURCE MANAGEMENT DIVISION  
 2811 AGRICULTURE DR.  
 MADISON, WI 53708—8911  
 CHRISTOPHER.CLAYTON@WI.GOV  
 (608) 224-4630

<b>County</b>	<b>District</b> (A separate report must be submitted for each district.)	<b>Date:</b>
Dane	4	10/4/2017

I. Financial Statement		
	DEBTS	CREDITS
Starting balance on September 1st, 2016		\$6,611.99
Assessments Collected		\$ 36.58
Interest earned on assessments		
Interest earned on borrowed funds		
Other Receipts		
<b>Total of all receipts</b>		<b>\$ 36.58</b>
Amount paid out for district activities	\$5,970.96	
Amount paid out to repay loans or bonds		
Other payables		
<b>Total of all expenditures</b>	<b>\$5,970.96</b>	
Ending balance on August 31, 2017		\$977.10
Uncollected Assessments		

II. The following bonds have been issued or paid during the preceding twelve months:

III. Attach sheets detailing work performed in the previous year. Include:

- A. Project description, including project cost
- B. Map showing the location of project
- C. Annual Inspection Report, major storm reports, and/or other inspection reports performed by the Drainage Board in the past twelve months

Name of Drainage Board Chairperson:	Date:
Scott Ringelstetter	
Signature of Drainage Board Chair (please print):	October 9, 2017
Scott Ringelstetter	

**NOTE:** Submit one copy of this report to DATCP, the county Zoning Administrator, the town board or town zoning committee, and the city council, plan commission, or plan committee in which district territory

ANNUAL REPORT

As of August 31, 2017

The Dane County Drainage Board submits the following annual report for the above identified drainage district for the twelve (12) month period ending August 31, 2017.

1. Work done in the district.

Two suck-holes along Mueller Road were repaired

2. A review and inspection of the district found the following:

Earlier work on the main tile on the Renk property south of Mueller Road has failed again. The plan is to determine the actual problem using a camera.

We checked the inlet by the Laufwnberg driveway, the inlet at Norway Road. The new homes on the west end of the district are dumping water from the detention ponds into the district.